

### What's New

---

1. App will show Wake On Motion (WoM) related connection instructions based on Cut-off Serial number of Driveri.
2. App will display a note for VIN scan, thus indicating the users to scan only barcode for the VIN.

**Installer report**  
Create installer report

Driveri# 16309264 will disconnect in 342 seconds.  
Tap this banner to increase time.  
Please do not press HOME button while connected to Driveri.

**Vehicle number**

I don't know Vehicle number

**VIN**

**Scan VIN**

● Scan Barcode for VIN. QR code is not accepted for VIN.

OR

I don't know VIN

**Class type\***

● Click here to see Vehicle Class examples

3. A Cancel button has been added on timeout screen. This will enable the user to exit the connection process.



### OOPS! CONNECTION TIMED OUT

Bluetooth connection failed for Driver: 16309264

Here are some troubleshooting tips to help you out:

- 1 Check if the device is powered ON or not**  
If not, then please turn it ON and press "TRY AGAIN" button below.
- 2 Did you open any other app during the connection process?**  
If yes, then please press "TRY AGAIN" button below and do not open any other app during the connection process.
- 3 Did you turn OFF and ON ignition before starting the connection process?**  
If not, please press "TRY AGAIN" button below and follow the instructions given.


TRY AGAIN

CANCEL

---

Version 5.7

4. Ford E450 Step van mapping has been changed to Class 5 from Class 3 in Vehicle Class Examples pop-up.



5. The description below Attach Images has been updated to: "Attach images showing Driveri mounted on the windshield with both inward and outward view, VIN Tag with GVWR info, Power connection location, CAN Bus connection, vehicle plate number etc. "
6. The banner text at the bottom of the page has been updated to "App version" instead of version to highlight App version on each screen.
7. Clear fields button in Report view has been removed.
8. Debug and Test Audio Command Options for D-210 product line.